FINITION CUIVREE

Le cuivrage est un processus de dépôt d'une couche de cuivre sur différents métaux pour des buts fonctionnels et décoratifs. Le cuivre est un élément chimique avec une haute conductivité thermique et électrique, est antibactérien, solide, ductile et non-magnétique.
La finition cuivrée est un revêtement en cuivre, non-laqué. Avec le temps le cuivre change naturellement de couleur, à partir d'un marron brillant il passe à des marrons plus foncés, puis des bleus et à la fin après des années des verts. Ce changement de couleur, à cause de l'oxydation naturelle appelée « patine », n'altère pas la propriété antimicrobienne qui reste constante.




Cuivre


Material	*U.S. EPA Classification*	*Thickness*	*Copper plating process*
CU ≥ 97%	**Antimicrobial Copper Alloys - Group I**	**Min 8 µm**	**Copper Plating**

***Standard Pba**

*Laboratory testing shows that, when cleaned regularly, antimicrobial copper surfaces kill greater than 99.9% of the following bacteria within 2 hours of exposure: MRSA, VRE, Staphylococcus aureus, Enterobacter aerogenes, Pseudomonas aeruginosa, and E. coli O157:H7. Antimicrobial copper surfaces are a supplement to and not a substitute for standard infection control practices and have been shown to reduce microbial contamination, but do not necessarily prevent cross contamination or infections; users must continue to follow all current infection control practices.

NETTOYAGE





Do not use: chlorine, water plus salt solution, acid or alcoholic solution to avoid damaging the copper plated finish.

MATERIELS ET FINITIONS

MATERIEL	FINITION		.XX	* couleurs indicatives
FINITION CUIVREE	Standard	Semi-Bright	**.58**	